



Bethlehem Pike Traffic Signal and Road Conditions

Motorists traveling along Bethlehem Pike in Lower Gwynedd Township should expect delays due to traffic signalization upgrades and upcoming road work. The signalization project will take approximately eight weeks. In addition, PennDot will begin milling work which will affect the loop system all along Bethlehem Pike causing timing of the signal loop system not to be triggered as usual along Bethlehem Pike from Route 309 all the way to Upper Dublin Township beginning April 9th (weather permitting). This stretch of roadway will then be paved approximately one week later. All milling and paving work will be conducted in the evening and overnight hours. We apologize for the inconvenience this may cause and we ask that everyone be patient during this process.